

► A 160th SOAR Soldier was killed in a single vehicle accident June 18 at 0400 local near Clayton, N.C. The Soldier was traveling in a newly purchased Jeep Wrangler when the vehicle left the road, struck a median and flipped several times. The Soldier and a civilian passenger were not wearing seatbelts and were thrown from the vehicle. The North Carolina State Police were unable to determine who was operating the vehicle. The Soldier was pronounced dead at the scene. Alcohol is not suspected to be a factor. **COST: 1 Soldier Killed** 1 Civilian Killed

► A 3rd BCT. 10th Mountain Division Soldier was injured in a roof cave-in accident on June 18 at 1015 local in Afghanistan. Following the accident, the Soldier was taken to a medical facility unconscious. unresponsive and having diffculty breathing.

## **COST: 1 Soldier Injured**

→Three 4th BDE. 10th Mountain Soldiers were killed and two injured as a

result of a single vehicle accident June 19 at 0730 local near Woodville, Texas. The Soldiers were traveling in a Mazda Millennia when another vehicle passed their car and cut into their lane causing the driver of the Mazda to brake. The car hydroplaned, left the highway and hit several trees before coming to a stop. Three Soldiers who were riding on the right side of the vehicle, one in the front seat and two in the back seat, were killed. The left back seat passenger was treated at a local medical center and released two days later. The driver was treated and released the same day. All occupants were wearing seatbelts.

**COST: 3 Soldiers Killed** 2 Soldiers Injured

→ A 172nd Brigade, 101st Airborne Division Soldier was injured in a flash fuel fire June 20 at 2135 local in Iraq. The Soldier was holding a flashlight at a fuel point when the fuel ignited. The accident is currently under investigation. **COST: 1 Soldier Injured** 

https://crc.army.mil

→ A Soldier was injured in an AMV accident June 21 at 1000 local in Iraq. The Soldier was the TC of a Dodge Durango traveling on a road when a 2-ton truck struck the vehicle on the passenger side.

## **COST: 1 Soldier Injured** 1 AMV Damaged

Two Soldiers were killed during rescue operations while attempting to board a USAREUR UH-60A MEDEVAC helicopter June 21 at 2325 local in Afghanistan, Two Soldiers. a PFC and PV2, had been wounded in action during combat operations conducted earlier that day. When MEDEVAC arrived, the flight medic, a SGT, was lowered to the around on the rescue hoist to retrieve the Soldiers. After successfully extracting the PV2. the SGT was again lowered on the hoist to extract the PFC. While performing the second lift, the rescue

hoist cable reportedly failed causing the PFC and SGT to fall 30-feet to the ground, fatally injuring both Soldiers. No further details are available at this time.

COST: 2 Soldiers Killed

→An Unmanned Aerial System (UAS) from the 1st BCT. 4th Infantry Division. crashed on June 21 at 2141 local. The UAS crashed after indication of an "autopilot" failure and before the operator was able to deploy the recovery chute.

**COST: Class B** Damage to UAS





